

Greenstar Rate Controller Manure Constituent Sensing



JOHN DEERE

Software Update

Package	Version
Greenstar Rate Controller	3.75P

Controller Software Reprogramming –

[software-download-installation-instructions-english.pdf \(deere.com\)](#)

Resolved Issues

The following issues are fixed in software update 3.75P:

- Resolved an issue where rate controller would not map nutrients unless starting with a nozzle flow test.